
PART
ONE

MECHANICAL
FUNDAMENTALS

INTRODUCTION

1-1 SCOPE OF THIS BOOK

Mechanical metallurgy is the area of metallurgy which is concerned primarily with the response of metals to forces or loads. The forces may arise from the use of the metal as a member or part in a structure or machine, in which case it is necessary to know something about the limiting values which can be withstood without failure. On the other hand, the objective may be to convert a cast ingot into a more useful shape, such as a flat plate, and here it is necessary to know the conditions of temperature and rate of loading which minimize the forces that are needed to do the job.

Mechanical metallurgy is *not* a subject which can be neatly isolated and studied by itself. It is a combination of many disciplines and many approaches to the problem of understanding the response of materials to forces. On the one hand is the approach used in strength of materials and in the theories of elasticity and plasticity, where a metal is considered to be a homogeneous material whose mechanical behavior can be rather precisely described on the basis of only a very few material constants. This approach is the basis for the rational design of structural members and machine parts. The topics of strength of materials, elasticity, and plasticity are treated in Part One of this book from a more generalized point of view than is usually considered in a first course in strength of materials. The material in Chaps. 1 to 3 can be considered the mathematical framework on which much of the remainder of the book rests. For students of engineering who have had an advanced course in strength of materials or machine design, it probably will be possible to skim rapidly over these chapters. However, for most students of metallurgy and for practicing engineers in industry, it is

worth spending the time to become familiar with the mathematics presented in Part One.

The theories of strength of materials, elasticity, and plasticity lose much of their power when the structure of the metal becomes an important consideration and it can no longer be considered a homogeneous medium. Examples of this are in the high-temperature behavior of metals, where the metallurgical structure may continuously change with time, or in the ductile-to-brittle transition, which occurs in carbon steel. The determination of the relationship between mechanical behavior and structure (as detected chiefly with microscopic and x-ray techniques) is the main responsibility of the mechanical metallurgist. When mechanical behavior is understood in terms of metallurgical structure, it is generally possible to improve the mechanical properties or at least to control them. Part Two of this book is concerned with the metallurgical fundamentals of the mechanical behavior of metals. Metallurgical students will find that some of the material in Part Two has been covered in a previous course in physical metallurgy, since mechanical metallurgy is part of the broader field of physical metallurgy. However, these subjects are considered in greater detail than is usually the case in a first course in physical metallurgy. In addition, certain topics which pertain more to physical metallurgy than mechanical metallurgy have been included in order to provide continuity and to assist nonmetallurgical students who may not have had a course in physical metallurgy.

The last three chapters of Part Two are concerned primarily with atomistic concepts of the flow and fracture of metals. Many of the developments in these areas have been the result of the alliance of the solid-state physicist with the metallurgist. This has been an area of great progress. The introduction of transmission electron microscopy has provided an important experimental tool for verifying theory and guiding analysis. A body of basic dislocation theory is presented which is useful for understanding the mechanical behavior of crystalline solids.

Basic data concerning the strength of metals and measurements for the routine control of mechanical properties are obtained from a relatively small number of standardized mechanical tests. Part Three, Applications to Materials Testing, considers each of the common mechanical tests, not from the usual standpoint of testing techniques, but instead from the consideration of what these tests tell about the service performance of metals and how metallurgical variables affect the results of these tests. Much of the material in Parts One and Two has been utilized in Part Three. It is assumed that the reader either has completed a conventional course in materials testing or will be concurrently taking a laboratory course in which familiarization with the testing techniques will be acquired.

Part Four considers the metallurgical and mechanical factors involved in forming metals into useful shapes. Attempts have been made to present mathematical analyses of the principal metalworking processes, although in certain cases this has not been possible, either because of the considerable detail required or because the analysis is beyond the scope of this book. No attempt has been made to include the extensive specialized technology associated with each metal-

working process, such as rolling or extrusion, although some effort has been made to give a general impression of the mechanical equipment required and to familiarize the reader with the specialized vocabulary of the metalworking field. Major emphasis has been placed on presenting a fairly simplified picture of the forces involved in each process and of how geometrical and metallurgical factors affect the forming loads and the success of the metalworking process.

1-2 STRENGTH OF MATERIALS—BASIC ASSUMPTIONS

Strength of materials is the body of knowledge which deals with the relation between internal forces, deformation, and external loads. In the general method of analysis used in strength of materials the first step is to assume that the member is in equilibrium. The equations of static equilibrium are applied to the forces acting on some part of the body in order to obtain a relationship between the external forces acting on the member and the internal forces resisting the action of the external loads. Since the equations of equilibrium must be expressed in terms of forces acting external to the body, it is necessary to make the internal resisting forces into external forces. This is done by passing a plane through the body at the point of interest. The part of the body lying on one side of the cutting plane is removed and replaced by the forces it exerted on the cut section of the part of the body that remains. Since the forces acting on the “free body” hold it in equilibrium, the equations of equilibrium may be applied to the problem.

The internal resisting forces are usually expressed by the *stress*¹ acting over a certain area, so that the internal force is the integral of the stress times the differential area over which it acts. In order to evaluate this integral, it is necessary to know the distribution of the stress over the area of the cutting plane. The stress distribution is arrived at by observing and measuring the strain distribution in the member, since stress cannot be physically measured. However, since stress is proportional to strain for the small deformations involved in most work, the determination of the strain distribution provides the stress distribution. The expression for the stress is then substituted into the equations of equilibrium, and they are solved for stress in terms of the loads and dimensions of the member.

Important assumptions in strength of materials are that the body which is being analyzed is continuous, homogeneous, and isotropic. A *continuous body* is one which does not contain voids or empty spaces of any kind. A body is *homogeneous* if it has identical properties at all points. A body is considered to be *isotropic* with respect to some property when that property does not vary with direction or orientation. A property which varies with orientation with respect to some system of axes is said to be *anisotropic*.

¹ For present purposes *stress* is defined as force per unit area. The companion term *strain* is defined as the change in length per unit length. More complete definitions will be given later.

While engineering materials such as steel, cast iron, and aluminum may appear to meet these conditions when viewed on a gross scale, it is readily apparent when they are viewed through a microscope that they are anything but homogeneous and isotropic. Most engineering metals are made up of more than one phase, with different mechanical properties, such that on a micro scale they are heterogeneous. Further, even a single-phase metal will usually exhibit chemical segregation, and therefore the properties will not be identical from point to point. Metals are made up of an aggregate of crystal grains having different properties in different crystallographic directions. The reason why the equations of strength of materials describe the behavior of real metals is that, in general, the crystal grains are so small that, for a specimen of any macroscopic volume, the materials are statistically homogeneous and isotropic. However, when metals are severely deformed in a particular direction, as in rolling or forging, the mechanical properties may be anisotropic on a macro scale. Other examples of anisotropic properties are fiber-reinforced composite materials and single crystals. Lack of continuity may be present in porous castings or powder metallurgy parts and, on an atomic level, at defects such as vacancies and dislocations.

1-3 ELASTIC AND PLASTIC BEHAVIOR

Experience shows that all solid materials can be deformed when subjected to external load. It is further found that up to certain limiting loads a solid will recover its original dimensions when the load is removed. The recovery of the original dimensions of a deformed body when the load is removed is known as *elastic behavior*. The limiting load beyond which the material no longer behaves elastically is the *elastic limit*. If the elastic limit is exceeded, the body will experience a permanent set or deformation when the load is removed. A body which is permanently deformed is said to have undergone *plastic deformation*.

For most materials, as long as the load does not exceed the elastic limit, the deformation is proportional to the load. This relationship is known as Hooke's law; it is more frequently stated as *stress is proportional to strain*. Hooke's law requires that the load-deformation relationship should be linear. However, it does not necessarily follow that all materials which behave elastically will have a linear stress-strain relationship. Rubber is an example of a material with a nonlinear stress-strain relationship that still satisfies the definition of an elastic material.

Elastic deformations in metals are quite small and require very sensitive instruments for their measurement. Ultrasensitive instruments have shown that the elastic limits of metals are much lower than the values usually measured in engineering tests of materials. As the measuring devices become more sensitive, the elastic limit is decreased, so that for most metals there is only a rather narrow range of loads over which Hooke's law strictly applies. This is, however, primarily of academic importance. Hooke's law remains a quite valid relationship for engineering design.




Figure 1-1 Cylindrical bar subjected to axial load.

Figure 1-2 Free-body diagram for Fig. 1-1.

1-4 AVERAGE STRESS AND STRAIN

As a starting point in the discussion of stress and strain, consider a uniform cylindrical bar which is subjected to an axial tensile load (Fig. 1-1). Assume that two gage marks are put on the surface of the bar in its unstrained state and that L_0 is the gage length between these marks. A load P is applied to one end of the bar, and the gage length undergoes a slight increase in length and decrease in diameter. The distance between the gage marks has increased by an amount δ , called the deformation. The *average linear strain* e is the ratio of the change in length to the original length.

$$e = \frac{\delta}{L_0} = \frac{\Delta L}{L_0} = \frac{L - L_0}{L_0} \quad (1-1)$$

Strain is a dimensionless quantity since both δ and L_0 are expressed in units of length.

Figure 1-2 shows the free-body diagram for the cylindrical bar shown in Fig. 1-1. The external load P is balanced by the internal resisting force $\int \sigma dA$, where σ is the stress normal to the cutting plane and A is the cross-sectional area of the bar. The equilibrium equation is

$$P = \int \sigma dA \quad (1-2)$$

If the stress is distributed uniformly over the area A , that is, if σ is constant, Eq. (1-2) becomes

$$P = \sigma \int dA = \sigma A$$

$$\sigma = \frac{P}{A} \quad (1-3)$$

In general, the stress will not be uniform over the area A , and therefore Eq. (1-3) represents an *average stress*. For the stress to be absolutely uniform, every longitudinal element in the bar would have to experience exactly the same strain, and the proportionality between stress and strain would have to be identical for each element. The inherent anisotropy between grains in a polycrystalline metal rules out the possibility of complete uniformity of stress over a body of macro-

scopic size. The presence of more than one phase also gives rise to nonuniformity of stress on a microscopic scale. If the bar is not straight or not centrally loaded, the strains will be different for certain longitudinal elements and the stress will not be uniform. An extreme disruption in the uniformity of the stress pattern occurs when there is an abrupt change in cross section. This results in a stress raiser or stress concentration (see Sec. 2-15).

Below the elastic limit Hooke's law can be considered valid, so that the average stress is proportional to the average strain,

$$\frac{\sigma}{e} = E = \text{constant} \quad (1-4)$$

The constant E is the *modulus of elasticity*, or *Young's modulus*.

1-5 TENSILE DEFORMATION OF DUCTILE METAL

The basic data on the mechanical properties of a ductile metal are obtained from a tension test, in which a suitably designed specimen is subjected to increasing axial load until it fractures. The load and elongation are measured at frequent intervals during the test and are expressed as average stress and strain according to the equations in the previous section. (More complete details on the tension test are given in Chap. 8.)

The data obtained from the tension test are generally plotted as a stress-strain diagram. Figure 1-3 shows a typical stress-strain curve for a metal such as aluminum or copper. The initial linear portion of the curve OA is the elastic region within which Hooke's law is obeyed. Point A is the elastic limit, defined as the greatest stress that the metal can withstand without experiencing a permanent strain when the load is removed. The determination of the elastic limit is quite tedious, not at all routine, and dependent on the sensitivity of the strain-measuring instrument. For these reasons it is often replaced by the *proportional limit*, point A' . The proportional limit is the stress at which the stress-strain curve deviates from linearity. The slope of the stress-strain curve in this region is the modulus of elasticity.




Figure 1-3 Typical tension stress-strain curve.

For engineering purposes the limit of usable elastic behavior is described by the *yield strength*, point *B*. The yield strength is defined as the stress which will produce a small amount of permanent deformation, generally equal to a strain of 0.002. In Fig. 1-3 this permanent strain, or offset, is *OC*. Plastic deformation begins when the elastic limit is exceeded. As the plastic deformation of the specimen increases, the metal becomes stronger (strain hardening) so that the load required to extend the specimen increases with further straining. Eventually the load reaches a maximum value. The maximum load divided by the original area of the specimen is the *ultimate tensile strength*. For a ductile metal the diameter of the specimen begins to decrease rapidly beyond maximum load, so that the load required to continue deformation drops off until the specimen fractures. Since the average stress is based on the original area of the specimen, it also decreases from maximum load to fracture.

1-6 DUCTILE VS. BRITTLE BEHAVIOR

The general behavior of materials under load can be classified as ductile or brittle depending upon whether or not the material exhibits the ability to undergo plastic deformation. Figure 1-3 illustrates the tension stress-strain curve of a ductile material. A completely brittle material would fracture almost at the elastic limit (Fig. 1-4*a*), while a brittle metal, such as white cast iron, shows some slight measure of plasticity before fracture (Fig. 1-4*b*). Adequate ductility is an important engineering consideration, because it allows the material to redistribute localized stresses. When localized stresses at notches and other accidental stress concentrations do not have to be considered, it is possible to design for static situations on the basis of average stresses. However, with brittle materials, localized stresses continue to build up when there is no local yielding. Finally, a crack forms at one or more points of stress concentration, and it spreads rapidly over the section. Even if no stress concentrations are present in a brittle material, fracture will still occur suddenly because the yield stress and tensile strength are practically identical.

It is important to note that brittleness is not an absolute property of a metal. A metal such as tungsten, which is brittle at room temperature, is ductile at an elevated temperature. A metal which is brittle in tension may be ductile under hydrostatic compression. Furthermore, a metal which is ductile in tension at room




Figure 1-4 (a) Stress-strain curve for completely brittle material (ideal behavior); (b) stress-strain curve for brittle metal with slight amount of ductility.

temperature can become brittle in the presence of notches, low temperature, high rates of loading, or embrittling agents such as hydrogen.

1-7 WHAT CONSTITUTES FAILURE?

Structural members and machine elements can fail to perform their intended functions in three general ways:

1. Excessive elastic deformation
2. Yielding, or excessive plastic deformation
3. Fracture

An understanding of the common types of failure is important in good design because it is always necessary to relate the loads and dimensions of the member to some significant material parameter which limits the load-carrying capacity of the member. For different types of failure, different significant parameters will be important.

Two general types of excessive elastic deformation may occur: (1) excessive deflection under condition of stable equilibrium, such as the deflection of beam under gradually applied loads; (2) sudden deflection, or *buckling*, under conditions of unstable equilibrium.

Excessive elastic deformation of a machine part can mean failure of the machine just as much as if the part completely fractured. For example, a shaft which is too flexible can cause rapid wear of the bearing, or the excessive deflection of closely mating parts can result in interference and damage to the parts. The sudden buckling type of failure may occur in a slender column when the axial load exceeds the Euler critical load or when the external pressure acting against a thin-walled shell exceeds a critical value. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. Generally, little metallurgical control can be exercised over the elastic modulus. The most effective way to increase the stiffness of a member is usually by changing its shape and increasing the dimensions of its cross section.

Yielding, or excessive plastic deformation, occurs when the elastic limit of the metal has been exceeded. Yielding produces permanent change of shape, which may prevent the part from functioning properly any longer. In a ductile metal under conditions of static loading at room temperature yielding rarely results in fracture, because the metal strain hardens as it deforms, and an increased stress is required to produce further deformation. Failure by excessive plastic deformation is controlled by the yield strength of the metal for a uniaxial condition of loading. For more complex loading conditions the yield strength is still the significant parameter, but it must be used with a suitable failure criterion (Sec. 3-4). At temperatures significantly greater than room temperature metals no longer exhibit strain hardening. Instead, metals can continuously deform at constant stress in a time-dependent yielding known as *creep*. The failure criterion under creep condi-